03500.017772. PATENT

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
	:	Examiner: W. David Coleman
TOHRU DEN ET AL.	)	Art Unit: 2823
Appln. No.: 10/533,565	,	Art Uliit. 2823
Tappan I (a). Tareet, e de	:	Conf. No.: 4469
Filed: December 12, 2003	)	
E NAME OF THE CONTAINING	:	
For: NANOSTRUCTURE CONTAINING	)	
COLUMNAR MEMBERS SURROUNDED	:	
BY A REGION, ELECTRONIC	)	
DEVICE AND METHOD OF	:	
MANUFACTURING THE SAME	)	
	:	
U.S. Patent No.: 7,348,670 B2	)	
	:	
Issued: March 25, 2008	)	July 22, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

The amount of \$100.00 to cover the statutory fee for such Certificate of

Correction is being paid concurrently; please charge any deficiency in the fee, and credit any

overpayment, to Deposit Account 06-1205.

Patentees' undersigned attorney may be reached in our New York office by

telephone at (212) 218-2100. All correspondence should continue to be directed to our

address given below.

Respectfully submitted,

/Jason M. Okun/

Jason M. Okun

Attorney for Patentees

Registration No. 48,512

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

Facsimile: (212) 218-2200

FCHS WS 2338785v1

- 2 -

#### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

**PATENT NO.** : US 7,348,670 B2

**DATED** : March 25, 2008

INVENTOR(S): TOHRU DEN ET AL. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON THE TITLE PAGE [54]:

Title, "NANOSTRUCTURE, ELECTRONIC DEVICE AND METHOD OF MANUFACTURING THE SAME" should read --NANOSTRUCTURE CONTAINING COLUMNAR MEMBERS SURROUNDED BY A REGION, ELECTRONIC DEVICE AND METHOD OF MANUFACTURING THE SAME.--.

#### COLUMN 1:

Line 1, "NANOSTRUCTURE," should read --NANOSTRUCTURE CONTAINING COLUMNAR MEMBERS SURROUNDED BY A REGION,--;

Line 7, "relates" should read --relates to--; and Line 49, "reach other," should read --each other.--.

#### COLUMN 2:

Line 51, "growth stating" should read --growth starting--; and Line 60, "is which" should read --in which--.

#### COLUMN 3:

Line 15, "conceivable. For" should read --conceivable, for--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,348,670 B2</u>

No. of add'l. copies @ 30¢ per page



## 

#### UNITED STATES PATENT AND TRADEMARK OFFICE

### **CERTIFICATE OF CORRECTION**

**PATENT NO.** : US 7,348,670 B2

**DATED** : March 25, 2008

INVENTOR(S): TOHRU DEN ET AL. Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7:

Line 8, "row material" should read --raw material--; and Line 13, "amount a" should read --amount of a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,348,670 B2</u>

No. of add'l. copies @ 30¢ per page

